

# Unique Aspects of Micromechanics in Ballistic Penetration

by P. W. Kingman

ARL-TR-1412

July 1997

DTIC QUALITY INSPECTED 3

Approved for public release; distribution is unlimited.

19970912 156

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

Citation of manufacturer's or trade names does not constitute an official endorsement or approval of the use thereof.

Destroy this report when it is no longer need. Do not return it to the originator.

### **Army Research Laboratory**

Aberdeen Proving Ground, MD 21005-5066

**ARL-TR-1412** 

July 1997

# Unique Aspects of Micromechanics in Ballistic Penetration

P. W. Kingman

Weapons and Materials Research Directorate, ARL

DTIC QUALITY INSPECTED 3

Approved for public release; distribution is unlimited.

#### **Abstract**

Ballistic experiments with tungsten penetrators composed of single crystals have been used to specify and constrain deformation modes in order to elucidate the role of flow and deformation mechanisms in penetration. The large differences in penetrator performance as a function of crystal symmetry are interpreted in terms of the structures observed and the basic deformation modes implied. The results suggest in very general terms the interactive role of material deformation parameters. The superior performance of the [001] orientation is attributed to the combination of yield strength with an unusually smooth lamellar flow after failure initiates. In contrast, the high yield strength of the [111] crystal is offset by the dissipation of energy in less efficient flow mechanisms and microstructural evolution. The analysis has implications for approaches to optimizing penetrator design through tailored materials and microstructures.

## Acknowledgments

The writer wishes to acknowledge supportive and stimulating discussions with colleagues, particularly W. Bruchey, R. Herring, and E. Horwath, and laboratory support provided by D. MacKenzie.

## **Table of Contents**

		Page
	Acknowledgments	iii
	List of Figures	vii
1.	Introduction	1
2.	Experimental Approach	2
3.	Experimental Results	3
3.1 3.2 3.3	[110] Penetrator	3 5 8
4.	Discussion	13
5.	Conclusion	15
6.	References	17
	Distribution List	19
	Report Documentation Page	25

# **List of Figures**

<u>Figure</u>		Page
1.	Results of Ballistic Tests Against Semi-Infinite RHA	2
2.	Axial Section of [110] Penetrator, Showing Remnant Crystal and Flow Pattern	4
3.	Layer Structure in Extrusion Tube of [110] Penetrator	4
4.	Axial Section: Wavy Appearance of Exfoliations in [110] Extrusion Tube	6
5.	Axial Section of [111] Penetrator: Flow Line Patterns and Internal Bands Near Lower Right Corner. Inset: Schematic of Residual	6
6.	X-ray Analysis of Separated Crystal Segment Ahead of the [111] Residual Rod	7
7.	Stereograms of Diffraction Patterns Taken in Sequence Across [001] Peripheral Flow Region	9
8.	Partial Axial Section of [100] Penetrator With Orientation Analysis for Selected Regions	11
9.	Convex Surface of [100] Penetrator Fragment (nose down): (a) Overview; (b) Tabular Packets; (c) Diffraction Pattern	12

### 1. Introduction

The material flow mechanisms occurring under ballistic regimes exert a strong influence on penetration performance. Directional properties of materials have previously been recognized as a factor in the penetration process, but understanding of their actual role has been severely limited by the complexities of both mechanics and materials.

In a prior series of experiments at the U.S. Army Research Laboratory (ARL), tungsten rods machined from crystals at specified orientations were fired into semi-infinite rolled homogeneous armor [1]. The rationale for experiments with single crystals is that effects of penetrator geometry, ballistic conditions, and material parameters such as composition, density, grain size, etc., can be minimized. All specimens can be completely identical except for the internal (crystallographic) symmetry. Crystal symmetry is fundamental in determining the microstructural initiation and modes of material flow in crystalline materials, and at high symmetry the imposed constraints are stringent and specific. While single crystals may have limited practical application, well-specified experiments can be of great value in isolating and understanding the fundamental role of various deformation modes and their constraints.

The ballistic experiments have been described previously [1]. Figure 1 graphically summarizes the results. Each crystal rod had a selected unique crystallographic direction parallel to the penetrator axis. The observed results are a strong function of crystallographic symmetry, and in contrast with quasi-static stress-strain tests, the [111] (three-fold symmetry axis) single crystal was not the best performer. The [001] (four-fold symmetry axis) rod actually exceeded current tungsten heavy alloy penetrators and approached the performance of depleted uranium [1].




Figure 1. Results of Ballistic Tests Against Semi-Infinite RHA.

### 2. Experimental Approach

Axial sections of the targets demonstrated the effects of crystallographic orientation on the general flow pattern [1, 2]. The residual back end of the penetrator, typically about one diameter (~6 mm) in length, remained at the bottom of the penetration cavity surrounded by a thin layer of flowed material that extended back along the cavity walls to form a continuous hollow tube with a pattern of scroll-like foliations on the inner surface. Details of the final residual shape, the general appearance of the internal foliations, and the geometry and surface characteristics of the penetration tunnel differed for each crystal orientation, suggesting that the substantial differences in macroscopic penetration behavior originate in microscopic factors governing the initiation and continuation of material flow in the lattice.

Extensive characterization of the penetrator remnants was performed, utilizing optical microscopy and a variety of electron-optical and diffraction techniques. Diffraction data provide a basis for analyzing crystal orientation, lattice inhomogeneity (localized bending and substructure), recrystallization, grain size, preferred orientation, etc. A diffraction pattern from a small region of a single crystal can be analyzed to indicate the orientation of that region relative to the specimen axis, and visual features of the pattern can provide valuable qualitative information about the lattice distortion. The following discussion focuses primarily on the interpretation of the diffraction-based information as a key in bringing together all of the observations to form a coherent picture of the deformation process for each of these orientations.

### 3. Experimental Results

3.1 [110] Penetrator. This residual penetrator was completely recrystallized except for a small region at one corner of the back end (Figure 2). The material in the etched band structure is polycrystalline, and the Debye-Scherrer (D-S) rings from various regions indicated a variety of substructures ranging from sharp, equiaxed recrystallized grains to broad cold-worked rings, generally with strong texture. The rear surface of the rod was a mass of irregular surfaces, implying that the residual rod was heavily cracked and fragmented. The small remaining crystal fragment was tilted and deformed, so no useful orientation information could be obtained. The bands and cracks (probably originally axial) in the upper right portion of Figure 2 are thought to have initiated early in the process, followed later by laminar flow with extensive recrystallization. Although verification by diffraction was not possible, the appearance of the bands suggests twins, which would agree with observations by other workers [3, 4]. Figure 3 is a scanning micrograph of the layered structure in the extrusion tube. Some layers consist of relatively equiaxed grains and intergranular fractures, while the middle layer contains an extended region of cleavage. This microstructure agrees well with the flow pattern seen in Figure 2: some lamellae, possibly twin bands, developed a textured substructure which cleaved, while the surrounding material eventually recrystallized into equiaxed grains, resulting in intergranular fracture. The varied structure and appearance of the D-S rings in X-ray diffraction patterns from




Figure 2. Axial Section of [110] Penetrator, Showing Remnant Crystal and Flow Pattern.



Figure 3. Layer Structure in Extrusion Tube of [110] Penetrator.

this residual also support that interpretation. The overall flow patterns and general appearance of the [110] extrusion tube are quite different from those of other orientations. The frond-like shape of the foliations suggests extensive ductile flow at this stage of the process (Figure 4).

3.2 [111] Penetrator. An axial section through the [111] residual penetrator is shown in Figure 5. Diffraction patterns showed that the well-defined, blunt-nosed residual rod (schematic inset in Figure 5) is a single crystal, with some uniform lattice distortion but little net lattice rotation. Material in the flowed regions was primarily polycrystalline, with some lamellar bands surrounded by regions of equiaxed recrystallized grains. A few relatively large lamellae, mostly embedded directly ahead of the residual rod, were still single crystals, although severely bent and deformed. These regions appear schematically below the residual crystal in the Figure 5 inset. Figure 6 shows a series of diffraction patterns from the largest crystal fragment. As a reference, the X-ray pattern at point (a) is typical of the main body of the residual rod. Diffraction patterns from points (b), (c), and (d), all within the largest fragment, showed heavily textured rings along with broad, structured discrete reflections. The crystal orientation changed continuously from point (b) to point (d). It appears that the separated segment was in the process of being forced out of the way of the oncoming rod, surrounded by material previously recrystallized.

The precise nature of the few narrow bands appearing in the residual crystal could not be determined, but close examination suggests that they are flow bands whose propagation separates a crystal segment from the main rod. In the micrograph of Figure 5, a pair of closely spaced bands appears in the lower right corner. On the far right are layers of material that has already been discarded and forced out of the path of the rod. Just above the tip of the band is a small void between the rod and the discarded material, possibly opened up as the segment in the process of discard began to move to the right. We can infer that the segment below the band is just beginning to separate, the deformed and partially recrystallized region embedded directly below the rod resulted from a preceding discard, and the entire continuous layer of material surrounding the residual and extending to form the hollow tube is the result of a succession of such events.



Figure 4. Axial Section: Wavy Appearance of Exfoliations in [110] Extrusion Tube.




Figure 5. Axial Section of [111] Penetrator: Flow Line Patterns and Internal Bands Near Lower Right Corner. Inset: Schematic of Residual.




Figure 6. X-ray Analysis of Separated Crystal Segment Ahead of the [111] Residual Rod.

3.3 [001] Penetrator. Contrasting with the [111] rod, optical micrographs of an axial section of the [001] penetrator showed no clearly outlined rod remnant. Instead, there is an assemblage of blocky segments defined by large cracks, and throughout much of the sample there occurs a fine-scale (~100 µm) network of narrow, straight crack segments intersecting at right angles (Figure 7). In the central residual rod, these cracks are parallel and perpendicular to the rod axis, but in the peripheral regions they become respectively radial and parallel to the cavity interface. On the left side of the extrusion tube, this rectangular pattern could be observed within the layers and exfoliations, while on the opposite side there appeared to be sequences of voids. X-ray patterns showed the persistence of discrete crystal reflections throughout the entire nose of the penetrator and well into the extrusion tube. In the residual rod remnant, the diffraction pattern was always sharp and well-defined, but even in the macroscopically flowed regions, discrete diffraction spots could be easily distinguished. Extensive analysis throughout the specimen established that the fine cracks were parallel to {001} cleavage planes in all cases. Where the cracks continuously varied in direction, the crystal orientation also continuously rotated, as shown by the sequence of orientations at the bottom of Figure 7 (the dot on each stereogram is the pole of the observation surface). These orientations were determined from a step-sequence of X-rays across the boxed region. The trace of the (001) plane (the lower edge of the standard triangle) exactly matches the crack direction with virtually no change in the appearance of the diffraction pattern except for rotation. Along the penetrator axis directly ahead of the residual rod, the orientation was maintained and the spots were uniformly broadened without asterism. The only exceptions occurred when the diffracting region included the immediate edges of large cracks, where patterns exhibited asterism and D-S rings from recrystallized material at the interface, and at the outer surface of the sample, where a thin layer of deformed material also produced D-S rings.

Along the left edge of the penetrator, lattice rotation can be documented continuously from the nose back into the hollow extrusion tube for several rod diameters without discontinuity, until the discrete spots finally disappear in strongly textured D-S patterns.




Figure 7. Stereograms of Diffraction Patterns Taken in Sequence Across [100] Peripheral Flow Region.

In the upper right corner of Figure 7, the microstructure appears inconsistent with the remainder of the sample, since the crack network is not evident. This region is shown in more detail in Figure 8a. X-ray analysis showed that above the severe inhomogeneity occurring adjacent to the residual rod, the lattice orientation abruptly changes by about 30°, so that the (001) cleavage plane is no longer normal to the rod axis. The void-like features occur because the cuboids tilt into the observation surface, and at many locations small segments were extracted during preparation. The micrograph in Figure 8 shows the changing crack patterns. On the left is a typical diffraction pattern from location "A" and the related stereogram. The dot is the pole of the observation surface, and the (100) plane is horizontal and nearly normal to the observation surface. On the right are (upper) the stereogram for region "B" and a sequence of stereograms from a traverse across the transition region "C." The accompanying typical diffraction pattern corresponds to the "double" stereogram plotted from the opposite ends of each elongated diffraction spot. The orientation of the crack patterns in the transition region can be seen to change in parallel with the (100) trace in the stereograms, which indicate (as does the shape of the spots) a single-axis rotation about the observation normal.

Examination of a second [001] penetrator further elucidated the nature of this rotation and the true three-dimensional character of the deformation process. This penetrator cracked during flight and impacted the target in two closely spaced coaxial segments, and thus the residual did not have full integrity. After sectioning, most of the residual dropped out intact, leaving a partial shell of deformed layers adhered to the concave surface at the bottom of the penetration tunnel in the target block. Figure 9a is a scanning image of the convex surface of this extracted fragment at low magnification (nose pointed down). The convex surface appears covered with tabular rectangular packets, often rotated relative to one another (Figure 9b). Although a thin surface layer was deformed and partially recrystallized, discrete diffraction spots were distinctly visible in these packets (Figure 9c). It appears that material flow in the [001] crystals is not purely radial but that the flow packets of {001} layers also have a rotational degree of freedom about the normal to the packet. This would imply a very substantial degree of independence for these entities after cleavage. The rectangular edges of the packets also appear to be defined by {001} cleavage planes, but this could not be directly confirmed.





Figure 8. Partial Axial Section of [100] Penetrator With Orientation Analysis for Selected Regions.








Figure 9. Convex Surface of [100] Penetrator Fragment (nose down): (a) Overview; (b) Tabular Packets; (c) Diffraction Pattern.

#### 4. Discussion

From the experimental observations, it is evident that the operative microstructural processes are unique for each symmetry orientation.

In the [111] crystal, three <111> directions occur symmetrically at 70.5° from the rod axis. Resolved shear stresses on dislocations having these three Burgers vectors are thus relatively low, resulting in a high yield strength, while ample generation of dislocations available for interaction enhances work hardening. The tip of the residual is blunt, and it appears that relatively thick segments of material separate from the rod along narrow shear localizations and are forced outward toward the cavity walls along the blunt surface angle of the rod remnant while undergoing extensive working and recrystallization. The three-dimensional geometry of the separating segments is undetermined, but the cavity walls, which appear wavy in the axial section, are actually covered with discrete craters rather than having a circumferential undulation. All of these features suggest a less-than-smooth process. This sample was also the only one to possess a distinct surface layer of diffused iron from the target block, as well as iron solidified inside open cracks, indicating substantial heat generation during penetration. All of these observations suggest relatively greater diversion of forward kinetic energy into heating, hot working, and microstructure evolution as radial mass transfer and penetrator erosion take place.

For the [110] orientation, both imaging and diffraction results indicate that the penetrator material has repeatedly recrystallized, deformed, and recrystallized again. Classically, [110] bcc crystals have a high yield strength but do not work harden because the necessary dislocation reactions are unavailable due to symmetry. At high impact velocities, twins may occur [3, 4]. The bands seen in the micrographs were too fine and inhomogeneous to analyze by X-ray diffraction, but the possibility that both twins and axial cracks occurred early in the deformation process would agree with other observations on bcc materials. The consequent loss of integrity could account for the poor penetration in spite of the ductile flow.

In the [001] penetrator, with four-fold symmetry, all four <111> directions are equally stressed, creating large numbers of dislocations able to react with one another. One possible reaction is the Cottrell reaction [5]

$$\frac{1}{2}$$
 a [111] +  $\frac{1}{2}$  a [1 $\overline{11}$ ]  $\rightarrow$  a [100], (1)

which produces a sessile dislocation. This sessile dislocation is associated with the initiation of {001} cleavage cracks in bcc crystals oriented with a tensile stress axis along the [001] direction [5, 6].

Under impact conditions it can be reasonably speculated that a large distribution of dislocations would immediately be created and move only a short distance before interacting to create an extended array of sessile dislocations. This array would then inhibit work hardening and create nucleation sites for cleavage cracks as the deviatoric stresses increase and material flow is initiated. The smooth lamellar bending and shear, along with the relative absence of substructure, complex lattice distortion, and recrystallization in X-ray patterns from much of the peripheral flow region, indicate that relatively little work hardening occurs in the [001] penetrator. In contrast with the [111] hole profile, the [001] penetration tunnel is narrow and exceptionally smooth, and there is less material interaction between the penetrator and the target. Rather than discontinuously shedding finite material segments, the [001] rod is postulated to flow by a smooth quasi-continuous process in which small, finite lattice elements defined by (001) cleavage planes undergo a combination of lamellar bending and rotation during flow with little internal disturbance. This is a highly efficient process, permitting maximum partition of energy into forward motion. The persistence of the rectangular crack pattern through the curved foliations in the extrusion tube is strong evidence that lamellar flow of finite entities with minimal lattice disruption is the dominant deformation mode and that continuous reorientation of these discrete entities was complete before any recrystallization occurred. The observed rotation of the lamellar packets also suggests a substantial degree of independence for these entities during deformation.

Recently, ballistic experiments have been done with oriented polycrystals composed of individual grains having a symmetry axis oriented along the penetrator axis, with unconstrained rotations about the axis [7]. Differences between the major symmetry directions still exist but are smaller, and the [001] specimens perform less advantageously. Since the (001) cleavage is still theoretically normal to the axis in all grains, it is not clear whether the decrease in performance derives solely from mismatch obstacles to direct radial shear or whether the additional rotation of the packet about the normal to the cleavage plane may be essential to easy flow, and may be constrained in the polycrystal.

### 5. Conclusion

Ballistic penetration tests using rods machined from tungsten single crystals at specified orientations have shown that crystallography, which governs microstructural failure and flow mechanisms, is a strong determinant of penetration behavior. As previously noted by Magness and others [8, 9], classical quasi-static data do not necessarily imply similar performance in ballistic penetration. The excellent performance of the [001] orientation has been shown to result from a unique deformation mode in which work hardening is suppressed and flow initiates at microscopic inhomogeneities. In this mode, small but distinct crystal entities shear and flow with minimal internal deformation. Although adiabatic shear does not occur, this mode similarly activates an energetically efficient, uniform flow. Maximizing the fraction of total energy partitioned into forward penetration results in a deep, narrow, smooth-walled penetration cavity similar to that produced by depleted uranium (DU).

Single-crystal experiments provide a unique opportunity to specify highly constrained deformation modes. Basic material mechanisms are thus isolated without introducing additional material variables. Understanding these fundamental mechanisms will lead to a basis for designing novel materials and composites for future application.

### 6. References

- 1. Bruchey, W. J., E. J. Horwath, and P. W. Kingman. "Orientation Dependence of Deformation and Penetration Behavior of Tungsten Single-Crystal Rods." *Tungsten and Tungsten Alloys, Recent Advances*, edited by A. Crowson and E. Chen, Warrendale, PA: TMS, 1991.
- Bruchey, W. J., R. A. Herring, P. W. Kingman, and E. J. Horwath. "Deformation Mechanisms in Tungsten Single Crystals in Ballistic Impact Experiments." High Strain Rate Behavior of Refractory Metals and Alloys, edited by R. Asfahnai et al., Warrendale, PA: TMS, 1992.
- 3. Vecchio, K. Private communication. University of California San Diego, San Diego, CA, 1993.
- 4. Subhash, G., Y. J. Lee, and G. Ravichandran. "Plastic Deformation of CVD Textured Tungsten-II. Characterization." *Acta Metallurgica et Materialia*, vol. 42, pp. 331–340, 1994.
- 5. Cottrell, A. H. "Theory of Brittle Fracture in Steel and Similar Metals." *Transactions of the AIME*, vol. 212, pp. 192–203, 1958.
- 6. Carrington, W., K. F. Hale, and D. McLean. "Arrangement of Dislocations in Iron." Proceedings of the Royal Society of London, Series A, Mathematical and Physical Sciences, vol. 259, pp. 203–227, 1960.
- 7. Leonard, W., L. Magness, M. Chang, and D. Kapoor. "The Performance of Oriented Columnar Grained Polycrystalline Tungsten Penetrators." *Proceedings of the 16th International Ballistics Symposium*, vol. 3, pp. 617–626, 1996.
- 8. Magness, L. S. "Properties and Performance of KE Penetrator Materials." *Tungsten and Tungsten Alloys*, Princeton, NJ: Metal Powder Industries Federation, pp. 15–22, 1992.
- 9. Magness, L. S., and T. S. Farrand. "Deformation Behavior and Its Relationship to the Penetration Performance of High-Density KE Penetrator Materials." *Proceedings of the 1990 Army Science Conference*, pp. 465–479, 1991.

## NO. OF COPIES ORGANIZATION

- 2 DEFENSE TECHNICAL INFORMATION CENTER DTIC DDA 8725 JOHN J KINGMAN RD STE 0944 FT BELVOIR VA 22060-6218
- 1 HQDA
  DAMO FDQ
  DENNIS SCHMIDT
  400 ARMY PENTAGON
  WASHINGTON DC 20310-0460
- 1 CECOM
  SP & TRRSTRL COMMCTN DIV
  AMSEL RD ST MC M
  H SOICHER
  FT MONMOUTH NJ 07703-5203
- 1 PRIN DPTY FOR TCHNLGY HQ US ARMY MATCOM AMCDCG T M FISETTE 5001 EISENHOWER AVE ALEXANDRIA VA 22333-0001
- 1 PRIN DPTY FOR ACQUSTN HQS
  US ARMY MATCOM
  AMCDCG A
  D ADAMS
  5001 EISENHOWER AVE
  ALEXANDRIA VA 22333-0001
- 1 DPTY CG FOR RDE HQS
  US ARMY MATCOM
  AMCRD
  BG BEAUCHAMP
  5001 EISENHOWER AVE
  ALEXANDRIA VA 22333-0001
- 1 ASST DPTY CG FOR RDE HQS
  US ARMY MATCOM
  AMCRD
  COL S MANESS
  5001 EISENHOWER AVE
  ALEXANDRIA VA 22333-0001

# NO. OF COPIES ORGANIZATION

- 1 DPTY ASSIST SCY FOR R&T SARD TT F MILTON THE PENTAGON RM 3E479 WASHINGTON DC 20310-0103
- 1 DPTY ASSIST SCY FOR R&T SARD TT D CHAIT THE PENTAGON WASHINGTON DC 20310-0103
- 1 DPTY ASSIST SCY FOR R&T SARD TT K KOMINOS THE PENTAGON WASHINGTON DC 20310-0103
- 1 DPTY ASSIST SCY FOR R&T SARD TT B REISMAN THE PENTAGON WASHINGTON DC 20310-0103
- 1 DPTY ASSIST SCY FOR R&T SARD TT T KILLION THE PENTAGON WASHINGTON DC 20310-0103
- OSD
  OUSD(A&T)/ODDDR&E(R)
  J LUPO
  THE PENTAGON
  WASHINGTON DC 20301-7100
- 1 INST FOR ADVNCD TCHNLGY THE UNIV OF TEXAS AT AUSTIN PO BOX 202797 AUSTIN TX 78720-2797
- 1 DUSD SPACE 1E765 J G MCNEFF 3900 DEFENSE PENTAGON WASHINGTON DC 20301-3900
- 1 USAASA MOAS AI W PARRON 9325 GUNSTON RD STE N319 FT BELVOIR VA 22060-5582

# NO. OF COPIES ORGANIZATION

- 1 CECOM PM GPS COL S YOUNG FT MONMOUTH NJ 07703
- 1 GPS JOINT PROG OFC DIR COL J CLAY 2435 VELA WAY STE 1613 LOS ANGELES AFB CA 90245-5500
- 1 ELECTRONIC SYS DIV DIR CECOM RDEC J NIEMELA FT MONMOUTH NJ 07703
- 3 DARPA L STOTTS J PENNELLA B KASPAR 3701 N FAIRFAX DR ARLINGTON VA 22203-1714
- 1 SPCL ASST TO WING CMNDR 50SW/CCX CAPT P H BERNSTEIN 300 O'MALLEY AVE STE 20 FALCON AFB CO 80912-3020
- 1 USAF SMC/CED
  DMA/JPO
  M ISON
  2435 VELA WAY STE 1613
  LOS ANGELES AFB CA 90245-5500
- 1 US MILITARY ACADEMY
  MATH SCI CTR OF EXCELLENCE
  DEPT OF MATHEMATICAL SCI
  MDN A MAJ DON ENGEN
  THAYER HALL
  WEST POINT NY 10996-1786
- 1 DIRECTOR
  US ARMY RESEARCH LAB
  AMSRL CS AL TP
  2800 POWDER MILL RD
  ADELPHI MD 20783-1145

# NO. OF COPIES ORGANIZATION

- 1 DIRECTOR
  US ARMY RESEARCH LAB
  AMSRL CS AL TA
  2800 POWDER MILL RD
  ADELPHI MD 20783-1145
- 3 DIRECTOR
  US ARMY RESEARCH LAB
  AMSRL CI LL
  2800 POWDER MILL RD
  ADELPHI MD 20783-1145

#### ABERDEEN PROVING GROUND

2 DIR USARL AMSRL CI LP (305)

#### NO. OF NO. OF COPIES ORGANIZATION COPIES ORGANIZATION CDR US ARO ATTN J CHANDRA JHU DEPT OF MECH ENG A CROWSON ATTN K HEMKER K IYER PO BOX 12211 K T RAMESH RESEARCH TRIANGLE PARK NC LATROBE 104 27709-2211 34TH & CHARLES ST **BALTIMORE MD 21218** 3 DIR WL MNMW MICHIGAN TECH UNIV ATTN W COOK J FOSTER JR DEPT OF MECH ENG ATTN G SUBHASH TECH LIB EGLIN AFB FL 32542-5434 **HOUGHTON MI 49931** DIR LANL 1 PURDUE UNIV ATTN P DUNN **DEPT OF MATLS ENGRNG** W HOGAN ATTN K BOWMAN **WEST LAFAYETTE IN 47907** PO BOX 1663 G770 LOS ALAMOS NM 87545 SW RSRCH INSTI DIR LLNL ATTN C ANDERSON ATTN C CLINE J LANKFORD PO DWR 28510 R GOGOLEWSKI **BOX 808 SAN ANTONIO TX 78228-0510** LIVERMORE CA 94550 2 UNIV OF CA SAN DIEGO **BROWN UNIV** DEPT OF APLD MCHNCS 1 & ENGRNG SCI B 010 **DIV OF ENGRNG** ATTN R CLIFTON ATTN M MEYER PROVIDENCE RI 02912 K VECCHIO LA JOLLA CA 92093 IAT ATTN S BLESS ADLEMAN ASSOC 1 T KIEHNE ATTN C CLINE 3301 EL CAMINO REAL STE 280 M J NORMANDIA ATHERTON CA 94027 R SUBRAMANIAN 4030 2 W BRAKER LN **AUSTIN TX 78759-5329** 3 **BATTELLE PNL** ATTN G DUDDER JHU W GURWELL 3 DEPT OF MAT SCI R SHIPPELL **RICHLAND WA 99352** ATTN RE GREEN R POND CONCURRENT TECH CORP J WINTER ATTN T MCCABE MD HALL 34TH & CHARLES ST 1450 SCALP AVE

**BALTIMORE MD 21218** 

**JOHNSTOWN PA 15904** 

#### NO. OF

#### COPIES ORGANIZATION

1 ZERNOW TECH SVC INC ATTN L ZERNOW 425 W BENITA STE 208 SAN DIMAS CA 91773

#### ABERDEEN PROVING GROUND

#### 39 DIR USARL

ATTN: AMSRL-WM-M, J MCCAULEY

AMSRL-WM-MA-CB.

R DOWDING

P WOOLSEY

AMSRL-WM-ME,

R ADLER

E CHIN

M WELLS

AMSRL-WM-T, W F MORRISON

AMSRL-WM-TA,

S BILYK

W BRUCHEY

**G BULMASH** 

**G FILBEY** 

W GILLICH

**E HORWATH** 

Y HUANG

D MACKENZIE

H MEYER

**E RAPACKI** 

**W ROWE** 

AMSRL-WM-TC,

**FGRACE** 

**E KENNEDY** 

L MAGNESS

AMSRL-WM-TD

A M DEITRICH

K FRANK

T FARRAND

P KINGMAN (4 CP)

S SCHOENFELD

M SCHEIDLER

J WALTER

T WRIGHT

AMSRL-WM-MF,

S CHOU

D DANDEKAR

**D GROVE** 

A RAJENDRAN

T WEERASOORIYA

AMSRL-WM-WD, L KECSKES

# NO. OF COPIES ORGANIZATION

- 2 CDR
  DRA FRT HALSTEAD
  ATTN A BENTLEY
  M HOGWOOD
  SEVENOAKS KENT TN14 7BP
  UNITED KINGDOM
- 1 DIR MRL
  ATTN R WOODWARD
  PO BOX 50
  ASCOT VALE VIC 3052
  AUSTRALIA

#### Form Approved REPORT DOCUMENTATION PAGE OMB No. 0704-0188 Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources gethering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway. Suite 1204. Artington. VA 22202-4392, and to the Office of Management and Budget. Paperwork Reduction Projection 74-0189. Washington. DC 20503. 3. REPORT TYPE AND DATES COVERED 2. REPORT DATE 1. AGENCY USE ONLY (Leave blank) June 1997 Final, March - August 1996 5. FUNDING NUMBERS 4 TITLE AND SUBTITLE Unique Aspects of Micromechanics in Ballistic Penetration 61102AH43 6. AUTHOR(S) P. W. Kingman 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) 8. PERFORMING ORGANIZATION REPORT NUMBER U.S. Army Research Laboratory ARL-TR-1412 ATTN: AMSRL-WM-TA Aberdeen Proving Ground, MD 21005-5066 10.SPONSORING/MONITORING 9. SPONSORING/MONITORING AGENCY NAMES(S) AND ADDRESS(ES) AGENCY REPORT NUMBER 11. SUPPLEMENTARY NOTES 12a, DISTRIBUTION/AVAILABILITY STATEMENT 12b. DISTRIBUTION CODE Approved for public release; distribution is unlimited. 13. ABSTRACT (Maximum 200 words) Ballistic experiments with tungsten penetrators composed of single crystals have been used to specify and constrain deformation modes in order to elucidate the role of flow and deformation mechanisms in penetration. The large differences in penetrator performance as a function of crystal symmetry are interpreted in terms of the structures observed and the basic deformation modes implied. The results suggest in very general terms the interactive role of material deformation parameters. The superior performance of the [001] orientation is attributed to the combination of yield strength with an unusually smooth lamellar flow after failure initiates. In contrast, the high yield strength of the [111] crystal is offset by the dissipation of energy in less efficient flow mechanisms and microstructural evolution. The analysis has implications for approaches to optimizing penetrator design through tailored materials and microstructures. 15. NUMBER OF PAGES 14. SUBJECT TERMS 27 micromechanics, anisotropy, ballistics, penetration, single crystal, tungsten 16. PRICE CODE 18. SECURITY CLASSIFICATION 19. SECURITY CLASSIFICATION 20. LIMITATION OF ABSTRACT 17. SECURITY CLASSIFICATION **OF ABSTRACT** OF REPORT OF THIS PAGE

Standard Form 298 (Rev. 2-89) Prescribed by ANSI Std. 239-18

UNCLASSIFIED

NSN 7540-01-280-5500

UNCLASSIFIED

**UNCLASSIFIED** 

#### USER EVALUATION SHEET/CHANGE OF ADDRESS

This Laboratory undertakes a continuing effort to improve the quality of the reports it publishes.	Your comments/answers
to the items/questions below will aid us in our efforts.	

thor ARL-TR-1412 (Kingman)	Date of Report <u>June 1997</u>
need? (Comment on purpose, related project, o	
eport being used? (Information source, design da	
his report led to any quantitative savings as far eved, etc? If so, please elaborate.	
at do you think should be changed to improve fur	
Organization	
Name	E-mail Name
Street or P.O. Box No.	
City, State, Zip Code	
Address or Address Correction, please provide th	ne Current or Correct address above and the Old
Organization	
Name	<del></del>
Street or P.O. Box No.	
Dutet of 1.0. Don 110.	
	need? (Comment on purpose, related project, of sport being used? (Information source, design design this report led to any quantitative savings as far eved, etc? If so, please elaborate.  Organization  Name  Street or P.O. Box No.  City, State, Zip Code  Address or Address Correction, please provide the organization  Name

(Remove this sheet, fold as indicated, tape closed, and mail.)
(DO NOT STAPLE)

#### **DEPARTMENT OF THE ARMY**

OFFICIAL BUSINESS



POSTAGE WILL BE PAID BY ADDRESSEE

DIRECTOR
US ARMY RESEARCH LABORATORY
ATTN AMSRL WM TA
ABERDEEN PROVING GROUND MD 21005-5066

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES